




095009-0530 Injection Repair Kit G2 Series Technical Data

SKU: G1S60030020DXB

Injection Repair Kit





095009-0530 Injection Repair Kit G2 Series Technical Data

Content

1. 095009-0530 Injection Repair Kit Introduction	2
1.1. 095009-0530 Injection Repair Kit Basic Information	2
1.2. 095009-0530 Injection Repair Kit Common Part Number	2
1.3. 095009-0530 Injection Repair Kit Number Common Writing	2
1.4. 095009-0530 Injection Repair Kit Parameter	2
1.5. 095009-0530 Injection Repair Kit Specifications and Dimensions Parameter	2
1.6. 095009-0530 Injection Repair Kit Quality Control	2
1.7. 095009-0530 Injection Repair Kit Customized Service	3
1.8. 095009-0530 Injection Repair Kit Package List & Package Size	4
1.9. 095009-0530 Injection Repair Kit Testing Standard and Certificate	5
1.10. 095009-0530 Injection Repair Kit Warranty Description	6
2. 095009-0530 Injection Repair Kit Technical Support	7
2.1. 095009-0530 Injection Repair Kit Installation Precautions	7
2.2. Reasons For 095009-0530 Injection Repair Kit Not Working Normally	7
2.3. Causes of 095009-0530 Injection Repair Kit Being Damaged	8
2.4. 095009-0530 Injection Repair Kit Storage Standard	8
2.5. 095009-0530 Injection Repair Kit Technical Support Obtaining Methods	9
3. 095009-0530 Injection Repair Kit Purchase and Delivery	9
3.1. 095009-0530 Injection Repair Kit Purchase Payment Term	9
3.2. 095009-0530 Injection Repair Kit Main Sales Markets	9
3.3. 095009-0530 Injection Repair Kit Declaration Requirements	9
3.4. 095009-0530 Injection Repair Kit Shipping Ways	9
3.5. 095009-0530 Injection Repair Kit Lead time	9
3.6. 095009-0530 Injection Repair Kit Logistics Time for Destination Out of China's Areas	10
3.7. 095009-0530 Injection Repair Kit Packing	10
4. Company Information	12
4.1. Company Introduction	12
4.2. Contact Information	12
5. Copyright Statement	13



095009-0530 Injection Repair Kit G2 Series Technical Data

1. 095009-0530 Injection Repair Kit Introduction

1.1. 095009-0530 Injection Repair Kit Basic Information

Injection Repair Kit Title	Common Rail 095009-0530 Injection Repair Kit G2 Series
SKU	G1S60030020DXB

1.2. 095009-0530 Injection Repair Kit Common Part Number

(1) Injection Repair Kit Applicable Injector Model

Injector Part Number	OE Number	OE Number
095000-0530	095009-0530	23670-30020

(2) Injection Repair Kit Matching Information

Vehicle Brand	Car Model	Engine Model	Production Date
For TOYOTA	LAND CRUISER	1KD-FTV	0008

1.3. 095009-0530 Injection Repair Kit Number Common Writing

095000-0530, 0950000530, 095000-0531, 0950000531, 095000-0532, 0950000532, 095000-0533, 0950000533, 095000-0534, 0950000534, 095000-0535, 0950000535, 095000-0536, 0950000536, 095000-0537, 0950000537, 095000-0538, 0950000538, 095000-0539, 0950000539, 095000-053#, 095000053#, 095009-0530, 0950090530, 095009-0531, 0950090531, 095009-0532, 0950090532, 095009-0533, 0950090533, 095009-0534, 0950090534, 095009-0535, 0950090535, 095009-0536, 0950090536, 095009-0537, 0950090537, 095009-0538, 0950090538, 095009-0539, 0950090539, 095009-053#, 095009053#, 23670-30020, 2367030020

1.4. 095009-0530 Injection Repair Kit Parameter

Injection Repair Kit Applicable System: [Common Rail System](#)

Injection Repair Kit Series: [G2 series](#)

Injection Repair Kit Type: [Electromagnetic Injection Repair Kit](#)

1.5. 095009-0530 Injection Repair Kit Specifications and Dimensions Parameter

Injection Repair Kit Size: [12cm* 8cm *3cm](#)

Single Injection Repair Kit Weight: [0.1kg](#)

Injection Repair Kit Weight Per Bag: [0.12kg](#)

Injection Repair Kit Quality: [China Made New](#)

Injection Repair Kit Package Size: [14cm* 10cm *3cm](#)

Injection Repair Kit Type: [High Pressure Common Rail Injection Repair Kit](#)

Injection Repair Kit MOQ: [4 pcs](#)

1.6. 095009-0530 Injection Repair Kit Quality Control

(1) Injection Repair Kit Testing

All parts of the injection repair kit have undergone electrical characteristics testing, precision testing,



high temperature testing, low temperature testing, withstand pressure testing, leakage testing, durability testing, and various working conditions testing.

(2) Injection Repair Kit Installation

In addition, the injection repair kit production and installation process is quality controlled. Our company strictly follows the standard product installation data and product installation steps for installation, such as injection repair kit stroke test, injection repair kit solenoid valve tightening torque, injection repair kit nozzle tightening torque.

(3) Injection Repair Kit Inspection

The factory inspection of the injection repair kit has undergone three inspections: full inspection, random inspection, and batch inspection. Different brands of test benches are used to test the same injection repair kit for more than three times for factory inspection, and the injection repair kit installation testing environment are progressed in dust-free workshop.

1.7. 095009-0530 Injection Repair Kit Customized Service

(1) Injection Repair Kit Customized Service Coverage: Meet OEM manufacturers' customization needs for shell engraving, logo engraving, injection repair kit internal packaging, injection repair kit external packaging and labels, etc.

No.	1	2
Image		
Name	Injection Repair Kit Assembly	Injection Repair Kit Package

(2) Injection Repair Kit Customized Service Requirements:

The purchase of customized [injection repair kit](#) is no less than 10 pieces.

The purchase of customized [injection repair kit package](#) is no less than 1000 pieces.

⚠ When customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

⚠ Once the customized injection repair kit is sold, it can't be returned or exchanged if there is no quality problems.



1.8. 095009-0530 Injection Repair Kit Package List & Package Size

(1) Injection Repair Kit Spare Parts List

No.	1	2	3
Image			
Name	Injection Repair Kit Assembly	Nozzle	Valve plate
Description	Injection repair kit assembly part number 095009-0530	Injector nozzle part number Order number: 093400-7530 Engraved number: DLLA155P753	Injector valve plate part number 295040-0500 (05#)
No.	4	5	6
Image			
Name	Nut	O-ring	White Anti-rust Bag
Description	Before installation, ensure that the length * diameter * thread of the tight cap is consistent	Ensure that the sealing performance between the Injector and the engine meets the standard	Prevent accessories from rusting
No.	7		
Image		/	/
Name	Lining	/	/
Description	Place overhaul kit accessories	/	/

- ⚠ Minors are prohibited from using the injection repair kit assembly, O-ring, nozzle protective cover, oil return protective cover, VCI anti-rust bag, and bubble bag to avoid personal injury.
- ⚠ O-rings and nozzle washer shim are one-time installation accessories and need to be replaced when installed again.
- ⚠ The nozzle protective cover and oil return protective cover are recyclable accessories and can be reused.
- ⚠ VCI anti-rust bags and bubble bags are non-degradable materials, please dispose of them properly after using.
- ⚠ The injection repair kit and the installation part duct must be treated with appropriate sealing oil during installation.

(2) Injection Repair Kit Package Size



Pic No.1

No.	Name	Injection Repair Kit Package Size (cm)
1	Injection Repair Kit Package	14*10*3

1.9. 095009-0530 Injection Repair Kit Testing Standard and Certificate

We can provide the factory quality inspection test report of each injection repair kit to ensure that each injection repair kit delivered meets the engine performance indicators.

BOTEN		测试报告		4.05.2019 10:42:09	
承审企业:					
电话:			地址:		
传真:			检测人:		
客户地址:					
电话:			送检单位:		
传真:			客户姓名:		
检测地址:					
台架名称:	融康路				
型号-零件号:					
配置内:					
检测结果					
检测器型号: CDS002-6511					
	检测前数据	参考值/数量	测试值/单位	检测后数据	
LEAK TEST:	38	— 5 —	6.5	20.0 ± 1.0	✓
Back:	38	— 4 —	35.7	20.0 ± 1.0	✓
WARM:	38	12.5 ± 10.5	0.9	— 0.0 —	✗
Max:	2015	218.5 ± 14.4	0.9	— 0.0 —	✓
TL:	26.4	24.0 ± 0.5	0.9	— 0.0 —	✓
LL:	141	11.7 ± 4.8	0.9	— 0.0 —	✓
VE:	6.2	4.5 ± 1.6	0.9	— 0.0 —	✓
☐ 维修前 ☐ 维修后 检测器型号:					

Pic No.2



1.10. 095009-0530 Injection Repair Kit Warranty Description

(1) Product Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports tested by the injection repair kit inspection equipment when the injection repair kit is abnormal during use as evidence to feed back to the salesman. Abnormal conditions are properly explained such as: 1. Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. Oil leakage etc.

(2) Injection Repair Kit Warranty Coverage

- ① After customer receives the injection repair kit within 15 days, if there is a performance failure and the product has no damage on surface, customer can choose to replace it or repair it;
- ② If the injection repair kit has performance problems during the warranty period (6-12 months), and it is confirmed to be product's problems after being tested, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;
- ③ If the injection repair kit shell has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

▲ **Tips:** For products not covered by warranty, our company can provide paid maintenance services. For products after paid repaired, the same performance problem will have a free warranty period within 3 months from the date of repairing.

(3) Injection Repair Kit Is Not Covered By Warranty

- ① The warranty period has expired.
- ② Injection repair kit failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.
- ③ Customer disassembles or repairs the injection repair kit personally resulting in damage to the Injection repair kit.
- ④ Injection repair kit damage caused by man-made reasons (throwing, strong magnetic field magnetization, set fire).
- ⑤ Injection repair kit failure or injection repair kit damage caused by non-injection repair kit design, technology, manufacturing, quality and other issues.
- ⑥ Injection repair kit failure due to system pressure exceeding system approved pressure.
- ⑦ Injection repair kit failure caused by system voltage exceeding approved voltage.
- ⑧ Injection repair kit failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.
- ⑨ Injection repair kit failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).
- ⑩ Injection repair kit failure caused by not following the installation angle specified in the vehicle engine maintenance manual.
- ⑪ Injection repair kit failure caused by not following the cleaning requirements specified in the vehicle engine maintenance manual.
- ⑫ Injection Repair Kit failure caused by failure to replace consumable parts as specified in the vehicle engine maintenance manual.
- ⑬ Injection repair kit failure caused by not complying with the intake system fit clearance and exhaust system fit clearance requirements specified in the vehicle engine maintenance manual.
- ⑭ Failure to replace the consumable parts and the fitting clearance of the oil inlet system pipeline and the injection repair kit connection in accordance with the fuel intake system specified in the vehicle



2. 095009-0530 Injection Repair Kit Technical Support

2.1. 095009-0530 Injection Repair Kit Installation Precautions

- (1) The replacement of the injection repair kit must strictly follow the electrical system, the approved pressure of the low-pressure fuel intake system, the approved pressure of the high-pressure fuel circuit system, and fuel system replacement consumables requirements (including the low-pressure fuel circuit system filter and the high-pressure fuel circuit) specified in the vehicle engine maintenance manual.
- (2) Replacement of wearing parts of the fuel system, cleaning requirements for the connection between the fuel system and the injection repair kit, the fitting clearance of the injection repair kit connection, the installation angle and tightening torque of the injection repair kit, the fitting clearance of the intake system, and the fitting clearance of the exhaust system to ensure the service life of the engine and the normal operation of the injection repair kit.
- (3) When installing the injection repair kit on the engine, it is necessary to clean the engine block, cylinder head and other parts connected to the injection repair kit, and ensure that there is no dust, carbon deposits, water, rust spots, etc.
- (4) Before installing, check whether the injection repair kit washer shim has been replaced and installed on the injection repair kit.
- (5) When installing the injection repair kit, apply lubricant between the injection repair kit, fuel nozzle sealing washer shim and O-ring.
- (6) Without replacing new washer shim can lead to: deformation of the tight cap of nozzle, deformation of nozzle, deformation of nozzle orifice, oil leakage and air leakage, which will cause serious damage to the injection repair kit and nozzle to break and cause damage to the engine.
- (7) When installing the injection repair kit on the engine, please carefully check the components related to the installation of the injection repair kit, such as the injection repair kit pressure plate, screw, injection repair kit rod and other accessories are not deformed, and install it in strict accordance with the operation steps of the engine maintenance manual.
- (8) It is forbidden to operate the bare injection repair kit for a long time in an environment with serious dust pollution and corrosion to iron products.
- (9) It is forbidden to operate the bare injection repair kit for a long time in a strong magnetic field environment.

2.2. Reasons For 095009-0530 Injection Repair Kit Not Working Normally

- (1) There is air in the oil circuit of the engine fuel system.
- (2) Vehicle injection repair kit oil supply system is not normal.
- (3) Engine common rail system oil leakage or pressure limiting valve damage.
- (4) There is a short circuit, cutting out and poor contact in the wiring harness connected to the injection repair kit of the vehicle.
- (5) The long-term placement of the injection repair kit causes the anti-rust oil to solidify, and the internal components are stuck or the oil holes are blocked.

⚠ Before installing, carefully check whether other components in the common rail system are damaged so as to prevent the injection repair kit from not working properly after being replaced.



2.3. Causes of 095009-0530 Injection Repair Kit Being Damaged

- (1) Didn't operate properly according to engine maintenance manual during disassembly or installation, resulting in damage to the injection repair kit.
- (2) The fuel oil used for the vehicle does not meet the standard cause damage to the injection repair kit, such as: the water content in the fuel oil exceeds the standard, iron powder, aluminum powder, sulfide impurities exceed the standard, etc.
- (3) The engine is not regularly maintained according to the engine maintenance manual (please refer to the vehicle maintenance manual for the maintenance mileage). For example, failure to replace the lubricating oil of the engine system for a long time will cause abnormal wear of the engine, excessive exhaust gas volume or a large amount of carbon deposits inside the engine. The filter is not replaced during maintenance or the replaced filter cannot reach the original filter standard. all above reasons can cause damage to the injection repair kit.
- (4) The abrasion of the oil pump produces iron powder and aluminum powder enter the injection repair kit and cause damage to the injection repair kit.
- (5) The deformation and abrasion of fuel tank result in iron powder or aluminum powder entering the injection repair kit and causing damage to it.
- (6) The injection repair kit is damaged due to replacement or adjustment of the relevant parts of the injection repair kit. For example, the valve clearance does not meet the standard after the engine is repaired, the replacement or modification of the wiring harness connected to the injection repair kit fails to meet the original standard.
- (7) The engine is overheated and overloaded for a long time working results in damage to the injection repair kit.
- (8) The injection repair kit will be damaged naturally at the end of its working life.
- (9) The injection repair kit is magnetized (injection repair kit parts' magnetic exceeded) causing the injection repair kit to not work properly.

⚠ **Before replacing the injection repair kit, please check the engine parts carefully according to the engine maintenance manual to avoid the injection repair kit being damaged again after replacement.**

2.4. 095009-0530 Injection Repair Kit Storage Standard

(1) Choose a Suitable Storage Place

The warehouse and cargo yard where the injection repair kits are stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict Requirements of Warehousing

Strict inspections should be carried out when the injection repair kits are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injection repair kits must be protected from damage.

(3) Keep The Warehouse Dry And Preventing Moisture

The relative humidity is usually below 70% for the injection repair kits placed in the room, and the corrosion of the injection repair kits is significantly reduced.

Injection repair kits must be stored in the warehouse, and they are forbidden to store in the same



warehouse with commodities with high water content.

(4) Stack Properly

After the injection repair kit is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injection repair kit from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse

If the injection repair kit package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

- ⚠ It is forbidden to leave the injection repair kit exposed in the air for a long time.
- ⚠ It is forbidden to store acid, alkali, salt and other substances with the injection repair kit.
- ⚠ The unpacked injection repair kit must be rust-proof during secondary storage.

2.5. 095009-0530 Injection Repair Kit Technical Support Obtaining Methods

- (1) Injection Repair Kit Technical Data: <https://www.injectionrepairkit.com/download/>
- (2) Injection Repair Kit Videos: <https://www.injectionrepairkit.com/videos/>
- (3) Injection Repair Kit Encyclopedia: <https://www.injectionrepairkit.com/category/news/encyclopedia/>

3. 095009-0530 Injection Repair Kit Purchase and Delivery

3.1. 095009-0530 Injection Repair Kit Purchase Payment Term

Payment Terms: T/T, PayPal, Alipay, WeChat

- ⚠ Please contact our salesmen for specific payment information.

3.2. 095009-0530 Injection Repair Kit Main Sales Markets

Injection Repair Kit Main Sales Markets: Asia, Europe, North America, South America, Africa etc.

3.3. 095009-0530 Injection Repair Kit Declaration Requirements

We can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4. 095009-0530 Injection Repair Kit Shipping Ways

Destination in China Areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations Out of China's Areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5. 095009-0530 Injection Repair Kit Lead time

Lead time: Send out within 3 – 7 working days after receiving payment (Except for special products and special cases) .



3.6. 095009-0530 Injection Repair Kit Logistics Time for Destination Out of China's Areas

DHL Logistics Time :

Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries
China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days

UPS Logistics Time: Country or Region of Departure: China's Mainland

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK	5-7Days	Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5-7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar	7-10 Days	Poland	5-7 Days
Indonesia	3-5 Days	Morocco	7-10 Days	Pakistan	7-10 Days
Kuwait	7-10 Days				

▲ The logistics time is for reference only and is subject to the actual arrival.

3.7. 095009-0530 Injection Repair Kit Packing

Domestic Express Packaging: Usually wrapped in waterproof scotch tape, such as picture No.3.

International Express Packaging: Wrapped with waterproof yellow tape After wrapping the black protective film, such as picture No. 4.


Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 5, also, the products can be packaged according to customers' requirements.

- ▲ The packing tray is made of plastic and can be recycled.
- ▲ Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.
- ▲ Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.



Pic No. 3

Domestic Express Packaging: Wrapped with Transparent tape



Pic No. 4

International Express Packaging: Wrapped with yellow tape after wrapping black protective film



Pic No. 5

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties



4. Company Information



Pic No. 6

4.1. Company Introduction

 **Mob Phone/WeChat:** +86-13410541523

 **HK Telephone:** +852-67653519

 **Telephone:** +86-755-23215133

 **Shenzhen Office:** 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China Mainland

 **Shenzhen Office:** Exit C, Qiao Touxu Metro Station, NO. 66 Chongqing Road, Fuhai Avenue, Bao'an District, Shenzhen, China Mainland

 **Hong Kong Office:** Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

 **After-sales Service Address:** Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: [1.10. 095009-0530 Injection Repair Kit Warranty Description](#))

4.2. Contact Information

Name	WeChat/ WhatsApp
Ruby	+86-13410541523



5. Copyright Statement

The file "[095009-0530 Injection Repair Kit G2 Series Technical Data](#)" published on this website ([www.injectionrepairkit.com](#)), including text, pictures, audio, video, programs, and web page layout design, etc., is the sole property of Shenzhen Shumatt Technology Co., Ltd. Visitors may use the content or services provided by this website for personal study, research or appreciation, as well as other non-commercial or non-profit purposes.

However, at the same time, visitors should abide by the provisions of copyright law and other relevant laws, and must not infringe the contents of this website and related legal rights of the right holder. In addition, when using any content or services of this website for other purposes, you must obtain the written permission from Shenzhen Shumatt Technology Co., Ltd. and the relevant rights holders, and pay remuneration.